



Designation: D5861 – 07 (Reapproved 2017)

Standard Guide for Significance of Particle Size Measurements of Coating Powders¹

This standard is issued under the fixed designation D5861; the number immediately following the designation indicates the year of original adoption or, in the case of revision, the year of last revision. A number in parentheses indicates the year of last reapproval. A superscript epsilon (ϵ) indicates an editorial change since the last revision or reapproval.

1. Scope

1.1 This guide covers the significance of referencing the techniques used whenever specifying the particle size distribution of a coating powder.

1.2 *This international standard was developed in accordance with internationally recognized principles on standardization established in the Decision on Principles for the Development of International Standards, Guides and Recommendations issued by the World Trade Organization Technical Barriers to Trade (TBT) Committee.*

2. Referenced Documents

2.1 *ASTM Standards:*²

D1921 Test Methods for Particle Size (Sieve Analysis) of Plastic Materials

D3451 Guide for Testing Coating Powders and Powder Coatings

3. Terminology

3.1 *Definitions:*

3.1.1 *coating powders, n*—these are finely divided particles of organic polymer that generally contain pigments, fillers, and additives and that remain finely divided during storage under suitable conditions.

3.1.2 *powder coatings, n*—these are coatings that are protective, decorative, or both; and that are formed by the application of a coating powder to a substrate and fused into continuous films by the application of heat or radiant energy.

4. Significance and Use

4.1 This guide describes the need to specify the measuring technique used whenever quoting the particle size distribution of a coating powder.

¹ This guide is under the jurisdiction of ASTM Committee D01 on Paint and Related Coatings, Materials, and Applications and is the direct responsibility of Subcommittee D01.51 on Powder Coatings.

Current edition approved June 1, 2017. Published June 2017. Originally approved in 1995. Last previous edition approved in 2013 as D5861 – 07 (2013). DOI: 10.1520/D5861-07R17.

² For referenced ASTM standards, visit the ASTM website, www.astm.org, or contact ASTM Customer Service at service@astm.org. For *Annual Book of ASTM Standards* volume information, refer to the standard's Document Summary page on the ASTM website.

4.2 This guide is for use by manufacturers of coating powders and by specifiers for process control and product acceptance.

5. Particle Size of Coating Powders

5.1 The size of the particles comprising a coating powder plays a critical role in the fluidization, application, and reclamation of the powder, and in the final appearance of the coated part. Coating powders are comprised of particles of widely differing sizes, from as low as about 1 μm to as high as about 150 μm . Collectively, the individual particles form a size distribution, defined by the percentages of particles present of a given size or within a given size range. There are generally few particles at the low and high ends of the distribution, the majority being in the 25 to 65- μm range. The distribution can be described by an actual plot of the particle size distribution, or by numerical attributes of the distribution, such as the calculated values of its mean, median, mode, and span. The mean represents the average particle size (the sum of all the particle sizes divided by the number of particles). The median represents a size such that half the particles are larger than it and half the particles are smaller than it. The mode represents the most frequently occurring particle size. For all coating powders these three figures are numerically different. The span is an indication of the width of the particle size distribution. Referring to **Table A1.1**, the span is calculated by subtracting the d10 from the d90 and then dividing by the d50 or median particle size.

5.2 The particle size distribution is generally chosen by the coating powder manufacturer from knowledge of the application technique, the required cured film thickness, surface appearance, and performance. Once the desired particle size distribution has been selected, it needs to be monitored to ensure consistency from batch to batch and, indeed, within each batch. Occasionally the coating powder applicator may specify the particle size from knowledge of the specific application equipment or customer requirements, or both.

5.3 It is important for all involved to understand that the numerical data comprising a particle size distribution are significantly dependent on the technique used to obtain them. It is, therefore, of little use to quote or specify a particle size distribution, and even less a single particle size, without also