

ASTM MANUAL
on
QUALITY CONTROL
OF MATERIALS



Prepared by
ASTM COMMITTEE E-11
On Quality Control of Materials

- Part 1—Presentation of Data
Part 2—Presenting $\pm$ Limits of Uncertainty
of an Observed Average
Part 3—Control Chart Method of Analysis and Presentation
of Data

Special Technical Publication 15-C

January, 1951

Published by the
AMERICAN SOCIETY FOR TESTING MATERIALS
1916 Race St., Philadelphia 3, Pa.